INSPECTION REPORT

| PERMIT NUMBER: | BP-10-00558 | OWNER'S NAME: | CARR |
|---|------------------|---------------|-------------------|
| DATE: | 8/3/2015 | TYPE: | Foundation walls |
| TIME STARTED: | 12:30 PM | INSPECTOR: | Jessica Contratto |
| MAP NUMBER: | 19-16-24050-0106 | | |
| 1. rebar ok | | | |
| 2. see straps at shear | | | |
| 3. engineer letter for piers sitting on rock, not below grade | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| INSTRUCTIONS: ok to pour | | | |
| | | | |
| NEXT INSPECTION: shearwalls | | | |
| RE-INSPECTION FEE DUE? VES \$ | | | |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: | | | |
| iessica.contratto @co.kittitas.wa.us | | | |
| INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 | | | |