INSPECTION REPORT

TYPE:

PERMIT NUMBER:

DATE:

BP-13-00199

9/11/2014

OWNER'S NAME: PAUL NW INVESTMENTS

Multiple (see notes)

TIME STARTED:		10:53 AM	INSPECTOR:	Amber Green	
MAP NUMBER:		20-15-190510072			
	Complete drywall above ceiling line at firewall.				
	2. Please remove fireplace installation manual from inside the unit.				
INSTRUCTIONS: Complete the R-Channel at the firewalls. Mud and tape drywall at firewall in attic area.					
	-	ire caulk around any penetration	S.		
NEXT INSPECTION: R-Channel, Mud & tape of attic firewall, Rough-In Fireplace					
RE-INS	SPECTION FEE	DUE? NO YES	5	\$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	amber.green @co.kittitas.wa.us				
		CTION REQUEST LINE: <u>www.co.kitt</u> 11 N. Ruby Street, Suite 2, Ellensburg, \			