INSPECTION REPORT

PERMIT NUMBER:	BP-13-00674	OWNER'S NAME:	BACK COUNTRY
DATE:	6/30/2014	TYPE:	Exterior shear
TIME STARTED:	1:00 PM	INSPECTOR:	
1. CS16	floor to floor stra	p missing at flex front	wall.
INSTRUCTIONS: Add CS16 strap, then OK TO COVER. Please ensure a complete set of the approved plans are on site for future inspections.			
NEXT INSPECTION: FRAME/PLUMB/MECH			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CON ADDRESS:	NTACT THE INSPECTOR AT THE FO	LLOWING E-MAIL co.kittitas.wa.us
INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506