INSPECTION REPORT

TYPE:

INSPECTOR:

PERMIT NUMBER:

TIME STARTED:

DATE:

BP-13-00707

7/28/2014

OWNER'S NAME: WALLACE

Exterior shear

Amber Green

MAP NUMBER: 20-14-13050-0032
1. P1-2 not blocked and nailed per plan at lower Guest Room.
2. Re-check nailing at P1-2 to either side of chimney chase.
3. 6/S2 not framed per plan.
4. P1-3 at rear of garage not nailed per plan, majority of panel covered without inspecti
on.
5. RBC clips per shear schedule per 4/S2
6. A35 clips per shear schedule per 5/S2.
7. Opening at P1-2 in guest room - obtain engineers approval.
8. Re-check P1-2 nailing at crawl space shearwalls at lower floor.
INSTRUCTIONS: Complete above and call for re-inspection. Will complete all other interior shearwall and hardware inspection with framing.
NEXT INSPECTION: Re-Shear
RE-INSPECTION FEE DUE? VES \$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:
amber.green @co.kittitas.wa.us
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506