## **INSPECTION REPORT**

| PERMIT NUMBER:  | BP-13-00709      | OWNER'S NAME: | COLLIER        |
|---|------------------|---------------|----------------|
| DATE:   | 11/13/2014       | TYPE:         | Exterior shear |
| TIME STARTED:   | 3:56 PM          | INSPECTOR:    | Lou Whitford   |
| MAP NUMBER:   | 17-18-09051-0001 |               |                |
| 1. OK- EXTERIOR SHEAR   |                  |               |                |
|   |                  |               |                |
|   |                  |               |                |
|   |                  |               |                |
|   |                  |               |                |
|   |                  |               |                |
|   |                  |               |                |
|   |                  |               |                |
|   |                  |               |                |
|   |                  |               |                |
|   |                  |               |                |
| INSTRUCTIONS:   |                  |               |                |
|   |                  |               |                |
| NEXT INSPECTION: FRAMING, PLUMB, MECH   |                  |               |                |
| RE-INSPECTION FEE   | OUE? NO YES      |               | \$             |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION      |                  |               |                |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:              |                  |               |                |
| ■ INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694    ● |                  |               |                |

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506