INSPECTION REPORT

| PERMIT NUMBER: | BP-13-00736 | OWNER'S NAME: | GOKEY |
|--|--|--------------------|------------------------|
| DATE: | 3/5/2015 | TYPE: | Floor framing |
| TIME STARTED: | 4:24 PM | INSPECTOR: | Justin Bennett |
| MAP NUMBER: | 16-19-11000-0001 | | |
| 1. Crawl | access Ok | | |
| 2. Floor framing Ok | | | |
| 3. Ok to cover | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| INSTRUCTIONS: OF | to cover | | |
| | | | |
| NEXT INSPECTION: | Exterior shear | | |
| RE-INSPECTION FEE I | DUE? NO YES | | \$ |
| IF REQ | UIRED, RE-INSPECTION FEES MUST BE | PAID PRIOR TO SCHE | DULING A RE-INSPECTION |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: | | | |
| justin.bennett @co.kittitas.wa.us | | | |
| | TION REQUEST LINE: <u>www.co.kitt</u> L N. Ruby Street, Suite 2, Ellensburg, V | | |