



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-13-00736 OWNER'S NAME: GOKEY  
DATE: 3/31/2015 TYPE: Exterior shear  
TIME STARTED: 11:30 AM INSPECTOR: Jessica Contratto  
MAP NUMBER: 16-19-02040-0028

	1. obtain fix for missing double 2X bottom plate at SW 2,3 and 4 shearwalls
	2. Obtain engineer approval for nailing top plate in lieu of clips or install clips per shearwall schedule
	3. take pics of CS14 strap with 8 bays of blocking in roof diaphragm over great room before covering
	4. add nailing for bottom plate attachment per shear schedule

INSTRUCTIONS: ok to cover exterior. See corrections above at next inspection

NEXT INSPECTION: frame/plumb/mech

RE-INSPECTION FEE DUE? ☒ NO ☐ YES \$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

\_\_\_\_\_ jessica.contratto @co.kittitas.wa.us

• INSPECTION REQUEST LINE: [www.co.kittitas.wa.us/cds/request.asp](http://www.co.kittitas.wa.us/cds/request.asp) or 509-962-7694 •  
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506