## **INSPECTION REPORT**

OWNER'S NAME: FREED LLC

TYPE: Exterior shear

PERMIT NUMBER: BP-13-00741

9/25/2015

DATE:

TIME STARTED:		12:17 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:		20-15-19051-0050		
	1. Tighten Up Nailing On P1-2 Wall at Entry.			
	2. Holdown Straps and HDU's Must Connect to (2) Full Height Studs. Condition Exists Throug			
	hout. Corner of Garage Specifically.			
	3. P1-4 on Upstairs Wall Not Sheeted.			
INSTRUCTIONS: DO NOT COVER EXTERIOR				
NEXT INSPECTION: Re Inspect/PL:umb/Mech				
RE-INSPECTION FEE DUE? YES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
<u>ieremv.haberman</u> @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				