INSPECTION REPORT

PERMIT NUMBER:		BP-14-00040	OWNER'S NAME:	VARNUM	
DATE:		9/15/2014	TYPE:	Frame-Plumb-Mech	
TIME STARTED:		2:58 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		17-19-02071-0003			
	1. DWV not on test				
	2. H2O at 50#-ok				
	3. still need to address dryer vent				
	4. determine where fire separation in garage will be, this will change/not change some cor				
	rections				
INSTRUCTIONS: complete above, call for re-inspection. Have answer on fire separation at this time. If not sheetrocking ceiling, duct penetrations will need to be addressed					
not one of the state of the sta					
NEXT INSPECTION: re-inspection					
RE-INSPECTION FEE D		OUE? NO VES		\$ 65.00	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jessica.contratto @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					