INSPECTION REPORT

PERMIT NUMBER:	BP-14-00083	OWNER'S NAME:	DAVIDSON
DATE:	10/15/2014	TYPE:	Frame-Plumb-Mech
TIME STARTED:	3:20 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-17-01000-0005		
1. DWV a	 ut 6#- ok		
2. H2O at 50#- ok			
3. nail plates at multiple locations			
4. shorten and strap bath fan flex on lower floor			
	·		
INSTRUCTIONS: ok to insulates. see corrections then			
NEXT INSPECTION: insulation			
RE-INSPECTION FEE D	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
■ INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ● 411 N. Ruby Street, Suite 2. Ellensburg, WA 98926 ● Main Office Line: 509-962-7506			