## **INSPECTION REPORT**

BP-14-00175

**PERMIT NUMBER:** 

OWNER'S NAME: THE PASS LLC

DATE:		10/7/2014	TYPE:	Exterior shear	
TIME STARTED:		1:08 PM	INSPECTOR:	Amber Green	
MAP NUMBER:		22-11-04055-0034			
	4 011 -1-1		'ala la a Cara		
	1. Sill plate nailing missing in multiple locations.				
	2. (2) rows nailing per shearwall schedule at P2 walls.				
	3. Re-check all other nailing.				
INSTRUCTIONS: Complete Above, Re-Inspection. DO NOT COVER.					
NEXT INSPECTION: RE-INSPECTION					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	amber.green @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					