INSPECTION REPORT

PERMIT NUMBER:	BP-14-00183	OWNER'S NAME:	BURNSTEAD
DATE:	10/3/2014	TYPE:	Frame-Plumb-Mech
TIME STARTED:	2:06 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-20059-0029		
1. gas at 22#/5 minok			
2. H2O is live			
3. DWV on stack- ok			
4. 6x6 missing at foyer downstairs			
5. (5) 2x6 under GLB under stairs			
6. H1 clips at trusses in vault			
INSTRUCTIONS: complete above, see at insulation			
NEXT INSPECTION: insulation			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			