## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00235	OWNER'S NAME:	CHILDERS
DATE:	10/14/2014	TYPE:	Multiple (see notes)
TIME STARTED:	4:48 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-13050-0043		
1. exterio	r and interior shear ok		
2. mecha	nical ok		
3. gas at	30#-ok		
4. DWV a	at 6#-ok		
5. H20 not at 50# minimum for test			
6. studor vents not allowed. How will kitchen sink be vented?			
7. framing/hardware ok			
8. 4 hold downs missing in kitchen area. see at insulation			
INSTRUCTIONS: address plumbing issues, ok to insulate			
NEXT INSPECTION: insulation, re-inspect plumbing			
RE-INSPECTION FEE	DUE? NO YES	S	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> </ul>			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506