INSPECTION REPORT

TYPE:

PERMIT NUMBER:

DATE:

BP-14-00257

8/21/2014

OWNER'S NAME:

STANCIL

Re-inspection

TIME STARTED:		10:20 AM	INSPECTOR:	Amber Green	
MAP NUMBER:		20-14-35052-0038			
1	Penetrations around ductwork have still not been sealed.				
2	2. Still have no record of plumbing permit for new tankless water heater.				
3	3. Supply duct has been sealed off - OK				
INSTRUCTIONS: Fire caulk or mud around penetrations. Obtain plumbing permit for tankless water heater. Re-Fee, Re-Inspection.					
neator. No ree, no mapoulon.					
NEXT INSPECTION: Re-Inspection					
RE-INSPECTION FEE DUE? NO V YES \$ 65.00					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
amber.green @co.kittitas.wa.us					
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					