INSPECTION REPORT

PERMIT NUMBER: BP-14-00397 OWNER'S NAME: CAREY

DATE:		7/21/2015	TYPE:	Re-inspection
TIME STARTED:		10:41 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:		21-14-34061-0004		
1.	1. Exterior Shear Ok			
2.	2. Window correction not complete			
3.	3. Ok to cover exterior			
INSTRUCTIONS: Provide engineers letter for window @ stairs/Ok to cover exterior				
NEXT INSPECTION: Plumb/Mech				
RE-INSPECTION FEE DUE? YES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iustin.bennett @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 				
411 N. Kuby Street, Suite 2, Eliensburg, WA 98926 • Main Office Line: 509-962-7506				