INSPECTION REPORT

PERMIT NUMBER:	BP-14-00400	OWNER'S NAME:	NEW SUNCADIA LLC
DATE:	10/24/2014	TYPE:	Framing
TIME STARTED:	2:42 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-29051-0015		
1. fireplac	ce not installed		
2. truss bracing ok			
3. beam to beam connection in upstairs overlook per 4/D3			
4. block between floors at point loads			
5. post down under girder truss in master bath linen closet			
6. porch roof rafter connections pe details on D6			
7. clips/hangers at stair stringers			
8. positive connection top plate to beam at overlook upstairs			
INSTRUCTIONS: complete above, call for re-inspection			
NEXT INSPECTION: re-inspection			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			