## **INSPECTION REPORT**

**PERMIT NUMBER:** 

BP-14-00401

OWNER'S NAME:

**SCHEMM** 

DATE:		12/12/2014	TYPE:	Shearwalls	
TIME STARTED:		11:05 AM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-14-24050-0206			
	1. Horizontal blocking and nailing missing around entire house. Marked with crayon				
	2. cross blocking at 48" in first joist bays parallel to shear walls exterior. kitchen				
	3. tighten up sill plate nailing on P1-6 walls in master wing				
INSTRUCTIONS: complete above. Do not cover, call for re-inspection					
NEXT INSPECTION: re-inspection					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jessica.contratto @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 ◆</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506</li> </ul>					
411 N. Ruby Street, Suite 2, Eliensburg, WA 98920 Wildin Office Line: 509-902-7506					