INSPECTION REPORT

PERMIT NUMBER:	BP-14-00431	OWNER'S NAME:	MOORE
DATE:	8/19/2014	TYPE:	Frame-Plumb-Mech
TIME STARTED:	10:24 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-18-18000-0003		
1. insulat	e ductwork and dryer ve	nt in attic	
2. duct in master bedroom cannot be against roof sheeting			
3. framing/trusses ok			
4. H2O is	s live		
5. DWV at 6#			
INSTRUCTIONS: complete above. see at insulation inspection. Ok to insulate			
NEXT INSPECTION:	insulation		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			