INSPECTION REPORT

PERMIT NUMBER:	BP-14-00449	OWNER'S NAME:	SINNETT
DATE:	9/15/2014	TYPE:	Floor framing
TIME STARTED:	1:42 PM	INSPECTOR:	Amber Green
MAP NUMBER:	20-14-14050-0925		
1. Provide	e connection detail from	steel beam to	posts from engineer.
2. Complete A35s per plan.			
3. Complete 6x8 posts under steel beam point loads.			
INSTRUCTIONS: Complete Above, then Ok to Cover			
NEXT INSPECTION: Exterior Shear			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
■ INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 411 N Ruby Street Suite 2 Ellensburg WA 98926 Main Office Line: 509-962-7506			