INSPECTION REPORT

PERMIT NUMBER:		BP-14-00449	OWNER'S NAME:	SINNETT
DATE:		7/6/2015	TYPE:	Insulation
TIME STARTED:		11:03 AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:		20-14-14050-0925		
	1. Firepla	ce Venting/Draftstop Not	Complete.	
	2. Missed Bearing Point on Truss E6,E7,E8, E9 & E10 Waiting On Engineering.			
	3. Knee Brace on E10 Truss Not Bearing, Waiting on Engineering.			
	4. Investigate Floor Framing Correction from September 2014			
	5. All other Corrections OK.			
	6. Interior Shear OK.			
INSTRUCTIONS: OK to Cover All Areas Not Pertaining to Pending Corrections.				
NEVT INCRECTION:				
NEXT INSPECTION: ReInspect				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
jeremy.haberman @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 				