## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00497	OWNER'S NAME:	BURNSTEAD
DATE:	1/22/2015	TYPE:	Framing
TIME STARTED:	12:07 PM	INSPECTOR:	Amber Green
MAP NUMBER:	20-15-20059-0021		
1. Plumb	ing Not On Test.		
2. Trusses OK.			
3. 4x10 Header Over Gable End to Deck.			
4. Rear Wall of Garage (2) Trimmers at Back Window.			
5. Deck Incomplete. Exteerior Deck Framing to be inspected at Final. Int./Ext. Strap to be			
verified at Insulation.			
6. Truss Ledger Detail to be verified at Insulation.			
7. Deck Post to Footing Connection Detail to be verified at Final			
INSTRUCTIONS: Complete Corrections. OK to Insulate.			
NEXT INSPECTION: Insulation.			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			