## **INSPECTION REPORT**

| PERMIT NUMBER:   | BP-14-00513   | OWNER'S NAME:  | RC TEN LLC        |
|--|---|----------------|-------------------|
| DATE:  | 1/16/2015   | TYPE:          | Framing           |
| TIME STARTED:  | 11:04 AM  | INSPECTOR:     | Jessica Contratto |
| MAP NUMBER:  | 18-18-34058-0002  |                |                   |
| 1. comple  | ete H1 in 2 places at sou   | th end mid wal | I                 |
| 2. corrections ok  |   |                |                   |
| 3. trusses   | s/framing ok  |                |                   |
|  |   |                |                   |
|  |   |                |                   |
|  |   |                |                   |
|  |   |                |                   |
|  |   |                |                   |
|  |   |                |                   |
|  |   |                |                   |
|  |   |                |                   |
|  |   |                |                   |
|  |   |                |                   |
| INSTRUCTIONS: ok to insulate   |   |                |                   |
|  |   |                |                   |
| NEXT INSPECTION:   | nsulation   |                |                   |
| RE-INSPECTION FEE  | DUE? NO YES   |                | \$                |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION |   |                |                   |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:         |   |                |                   |
| jessica.contratto @co.kittitas.wa.us   |   |                |                   |
|  | <b>TION REQUEST LINE: <u>www.co.kitt</u>i</b><br>I N. Ruby Street, Suite 2, Ellensburg, V |                | <del></del>       |