INSPECTION REPORT

PERMIT NUMBER:	BP-14-00569	OWNER'S NAME:	MACY
DATE:	2/12/2015	TYPE:	Framing
TIME STARTED:	11:07 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	16-20-03000-0016		
1. Point l	oad blocking under gird	er trusses in ga	rage
2. Window added in brace wall panel at Great room porch wall			
3. All column caps missing per plans			
4. Strap at top plate break at porch beam in living room			
5. All porches soffited prior to framing inspection			
6. Add hangers at glulam beam added between two posts at front porch			
	o not cover/remove portion of s an to county for approval/obtair	<u> </u>	ication/bring revised window wall gner for missing column caps
NEXT INSPECTION:	Reinspection		
RE-INSPECTION FEE	DUE? NO YE	S	\$
IF REQ	UIRED, RE-INSPECTION FEES MUST E	BE PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QU	ESTIONS? PLEASE CONTACT THE INSP	PECTOR AT THE FOLLOW	/ING E-MAIL ADDRESS:
justin.bennett @co.kittitas.wa.us			
	TION REQUEST LINE: www.co.kit 1 N. Ruby Street, Suite 2, Ellensburg,		