INSPECTION REPORT

PERMIT NUMBER:

BP-14-00569

OWNER'S NAME: MACY

DATE:		3/2/2015	TYPE:	Re-inspection
TIME STARTED:		2:55 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:		16-20-03000-0016		
1. Insulation OK.				
INSTRUCTIONS: Verify Fireplace Vent Insulation Collar Prior to Cover. OK to Cover.				
NEXT INSPECTION: Hydronic Rough In				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
jeremy.haberman @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 				
TIT IV. Numy Street, Suite 2, Enerosourg, WA 30320 V Wall Office Line. 303 302 7300				