INSPECTION REPORT

PERMIT NUMBER:		BP-14-00671	OWNER'S NAME:	COLLINS
DATE:		1/12/2015	TYPE:	Re-inspection
TIME STARTED:		11:28 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		19-15-06000-0067		
	1. trusses ok			
	2. mechanical ok			
	3. can lights cannot be in fire separation between garage and upstairs. Must be fire rated			
	or removed			
	4. obtain engineer ok for header size used in added door on south side			
INSTRUCTIONS: complete above, ok to insulate. See corrections then				
NEXT INSPECTION: insulation				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
jessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				