INSPECTION REPORT

PERMIT NUMBER:	BP-14-00682	OWNER'S NAME:	MCARTHUR
DATE:	7/1/2015	TYPE:	Mechanical and plumbir
TIME STARTED:	10:31 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-14050-0920		
1. gas need	s to be at 15# minimum		
2. DWV on stack-ok			
3. H2O is live-ok			
4. HRV installed in loft mechanical room			
5. exhaust fans ok			
6. plumbing ok			
INSTRUCTIONS: re-test gas line at framing			
NEXT INSPECTION: framing			
RE-INSPECTION FEE I	DUE? NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ◆ 			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506