INSPECTION REPORT

| PERMIT NUMBER: | BP-14-00710 | OWNER'S NAME: | CASCADE VIEW |
|--|-------------------------------|---------------|--------------|
| DATE: | 10/21/2014 | TYPE: | Footings |
| TIME STARTED: | 12:07 PM | INSPECTOR: | Mike Flory |
| MAP NUMBER: | 18-18-27071-0142 | | |
| 1. SETBA | ACKS OK | | |
| 2. FOOTINGS OK. WILL SEE INTERIOR FOOTINGS AT SLAB | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| INSTRUCTIONS: | | | |
| | | | |
| NEXT INSPECTION: SLAB | | | |
| RE-INSPECTION FEE | DUE? NO YES | | \$ |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: | | | |
| | mike.flory @co.kittitas.wa.us | | |
| INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 | | | |