## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00752	OWNER'S NAME:	SUNCADIAVISION1 LL
DATE:	3/31/2016	TYPE:	Final
TIME STARTED:	1:29 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-29051-0071		
<ol> <li>Containment pan needed under water heater if located on flooring that may be damaged by water per IRC P281.5</li> <li>Seal around duct and flue penetrations above furnace</li> <li>Ductwork in crawlspace not insulated</li> <li>seal around garage door opner wires in garage lid</li> <li>Provide install manual for indoor evaporative AC coil. P trap may be required on condensate line</li> <li>1 energy credit total met with furnace and water heater. 5 credit still needed</li> <li>Whole house fan needs to be on a timer. Vented windows are then required. Or install fresh air system on furnace</li> <li>Energy credit can be achieved by a fresh air system on furnace and achieving a 4.0 or better on the blower door</li> </ol>			
INSTRUCTIONS: Complete above, call for re-inspection			
NEXT INSPECTION: Re-inspect			
RE-INSPECTION FEE DUE? VIOLET NO YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION  QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506