## **INSPECTION REPORT**

**PERMIT NUMBER:** 

BP-14-00754

OWNER'S NAME: NEW SUNCADIA LLC

DATE:		2/4/2015	TYPE:	Floor framing	
TIME STARTED:		11:58 AM	INSPECTOR:	Justin Bennett	
MAP NUMBER:		20-14-13050-0015			
	1. finish A35s to rim joist where noted				
	2. complete A35s or LPT4 to blocking under shearwalls				
	3. add protection under joist hanger flanges				
INSTRUCTIONS: complete above, ok to cover. see clips at shearwall inspection. send pics of hanger protection					
	ρ				
NEXT INSPECTION: shearwalls					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	justin.bennett @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					
+11 N. Nuby Street, Suite 2, Lifetisburg, WA 30320 Vividit Office Life. 303-302-7300					