

KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-14-00754	OWNER'S NAME:	NEW SUNCADIA LLC
DATE:	5/7/2015	TYPE:	Shearwalls
TIME STARTED:	11:16 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-13050-0015		

1. Missing HDU8 in mechanical room	
2. Correctly install saddles in hold downs	
3. Floor to floor HDU2's incorrectly installed. Upper floor to lowr floor, not foundatio	
n	
4. complete holddowns in garage	
5. add nails and block where indicated on exterior	

INSTRUCTIONS: complete above, ok to cover exterior. See holddowns at next inspection

NEXT INSPECTION: plumb/mech

RE-INSPECTION FEE DUE?

V NO

YES

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

iessica.contratto @co.kittitas.wa.us

\$

• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506