INSPECTION REPORT

PERMIT NUMBE	^{R:} BP-14-00759	OWNER'S NAME:	CASCADE VIEW INC
DATE:	3/19/2015	TYPE:	Frame-Plumb-Mech
TIME STARTED:	12:28 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-18-27071-0141		
1. H2C	o at 52#-ok		
2. DW	V not on test		
3. mechanical ok			
4. vented windows or fresh air to each habitable room required with a whole house fan			
5. interior shear ok			
INSTRUCTIONS: ok to insulate, see DWV on test at next inspection			
NEXT INSPECTIO	N: insulation		
RE-INSPECTION I	FEE DUE? NO YES	5	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INS	PECTION REQUEST LINE: <u>www.co.kitt</u> 411 N. Ruby Street, Suite 2, Ellensburg, V		