## **INSPECTION REPORT**

TYPE:

BP-14-00765

5/27/2015

**PERMIT NUMBER:** 

DATE:

OWNER'S NAME:

**HALL** 

Framing

TIME STARTED:		2:42 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:		20-15-20058-0135		
	1. Verify	<b>Duct Chase Penetration</b>	s are foamed	at Insulation Inspection.
	2. Trusses OK.			
	3. Verify Island Range Vent Duct Work and Island Gas Line Prior to Final.			
	4. Added Gas Line will Need to be put on test.			
INSTRUCTIONS: All other Corrections OK. OK to Insulate.				
NEXT INSPECTION: Insulation.				
RE-INSPECTION FEE DUE? NO YES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
jeremy.haberman @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				