



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-14-00818

OWNER'S NAME: CAHILL

DATE: 11/2/2015

TYPE: Re-inspection

TIME STARTED: 11:18 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-15-20058-0094

	1. Blower door test required to be under 5 ACH. Currently exceeding 8
	2. Home inspector report found broken truss in attic. Building inspector has verified.
	Engineered fix from truss company required for repair
	3. Smell of gas present in house. Find and address
	4. Other previous corrections ok
	5. Permit required for firepit addition. Do not cover pipe prior to inspection. Gas pipe
	not allowed to penetrate foundation below grade

INSTRUCTIONS: Complete above. Call for re-inspection when completed. Firepit can be on separate permit

NEXT INSPECTION: re-inspection

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

• **INSPECTION REQUEST LINE:** www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506