INSPECTION REPORT

PERMIT NUMBER:

BP-14-00821

OWNER'S NAME: MIFFLIN

DATE:		2/12/2015	TYPE:	Exterior shear
TIME STARTED:		12:18 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:		17-20-30051-0001		
	1. Exterior shear ok			
	2. Straps installed at portal framing in garage - ok			
;	3. Ok to cover			
INSTRUCTIONS:				
NEXT INSPECTION: Framing/Plumbing/Mech				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
	justin.bennett @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 				