

KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-14-00821	OWNER'S NAME:	MIFFLIN
DATE:	3/4/2015	TYPE:	Frame-Plumb-Mech
TIME STARTED:	9:49 AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	17-20-30051-0001		

1. Range Duct Must Be Insulated. Will Verify at Insulation Inspection.			
2. Insulationa nd Continuous Vapor Barrier Required behind Bathtub			
3. DWV OK. 5#/15min.			
4. Supply OK. 100#/15min.			
5. A35s @ 24" O.C. Required on Living Room Gable Wall, See S3.			
INSTRUCTIONS: OK to Insulate. Expose A35s for Verification at Insulation Inspection.			
NEXT INSPECTION: Insulation.			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

jeremy.haberman @co.kittitas.wa.us

• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506