INSPECTION REPORT

PERMIT NUMBER:	BP-15-00017	OWNER'S NAME:	DONOVAN
DATE:	3/10/2015	TYPE:	Mechanical
TIME STARTED:	11:38 AM	INSPECTOR:	Lou Whitford
MAP NUMBER:	18-18-32051-0004		
1. does n	ot have 13" side clearan	ce.	
INSTRUCTIONS:			
NEXT INSPECTION:			
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQU	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSPE		
lou.whitford @co.kittitas.wa.us			
	TION REQUEST LINE: <u>www.co.kitti</u> L N. Ruby Street, Suite 2, Ellensburg, V		