



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00084

OWNER'S NAME: WALLACE

DATE: 9/15/2015

TYPE: Framing

TIME STARTED: 2:11 PM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 17-19-35000-0044

	1. Exterior Shear nailing OK.
	2. HDU's at Barn Doors Must Connect to Full Height Studs.
	3. NOTE: Per Engineers Letter Need for HDU's on Back of Barn Eliminated Due to Eliminated Window.
	4. Framing OK.

INSTRUCTIONS: Make HDU Corrections. Call for Reinspection. Then Complete Double Sided Shearwall. Double Sided Shearwall Can be Seen at Final Inspection.

NEXT INSPECTION: Re Inspection.

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ jeremy.haberman@co.kittitas.wa.us

• **INSPECTION REQUEST LINE:** www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506