INSPECTION REPORT

PERMIT NUMBER:		BP-15-00094	OWNER'S NAME:	EATON	
DATE:		7/21/2015	TYPE:	Exterior shear	
TIME STARTED:		9:50 AM	INSPECTOR:	Jeremy Haberman	
MAP NUMBER:		20-14-13050-0014			
	1. (2)CS16 l	Floor to Floor Strapping Indicate	ed at Front P1-4 V	Valls Not Possible. Engineer S	
	tamped Detail Required.				
	2. Permit Not On Site. Will Sign for Missing Inspections at a Later Inspection.				
	3. Permit Set Plans Ripped and Pages Missing. INTACT PERMIT SET DRAWINGS WILL BE REQUIRED				
	AT NEXT INSPECTION.				
	4. All Other Exterior and Interior Shear OK.				
INSTRUCTIONS: OK to Cover Exterior Except Front P1-4 Wall. Email Photo of Correction Then OK to Cover.					
					
NEXT INSPECTION: Plumb/Mech.					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jeremy.haberman @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					