INSPECTION REPORT

PERMI	T NUMBER:	BP-15-00094	OWNER'S NAME:	EATON	
DATE:		9/24/2015	TYPE:	Mechanical and plumbir	
TIME STARTED:		1:25 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-14-13050-0014			
	1. gas piping	not complete			
	2. fireplace draftstop not complete. Metal trim rings arond chimneys missing. Draftstop ne				
	eded between basement and main floor				
	3. Heat shield required on all chimney installations per install manual				
	4. 1" clearance to combustibles for chimneys				
	5. vent kitchen sink above garage under window and out exterior same as bath vent. Kitchen				
	wall not bearing due to beam				
	6. H2O at 80#-ok house and garage				
	7. DWV on stack in house-ok. Drain above garage to be re-routed				
INSTRUCTIONS: complete above					
NEXT INSPECTION: re-inspect mechanical/ garage DWV					
RE-INSPECTION FEE DUE? V NO YES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					