INSPECTION REPORT

PERMIT NUMBER:	BP-15-00102	OWNER'S NAME:	VANDENHAUTE
DATE:	11/1/2016	TYPE:	Floor framing
TIME STARTED:	9:58 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-15-20058-0113		
1. Complete bloc 2. Install CB66 (cking per 2/S3.0 © column near garage		
INSTRUCTIONS: Complete above/Once complete Ok to cover NEXT INSPECTION: Exterior Shear RE-INSPECTION FEE DUE? V NO YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>justin.bennett</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506