



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-15-00124

OWNER'S NAME: TYLER

DATE: 1/6/2016

TYPE: Floor framing

TIME STARTED: 12:27 PM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-15-29050-0029

	1. Floor framing ok
	2. Radon standpipe missing
	3. Stemwall insulation and radon vapor barrier to be seen after crawl is cleared of snow
	and dried in

INSTRUCTIONS: ok to cover floor

NEXT INSPECTION: shearwalls/ Radon barrier at some point

RE-INSPECTION FEE DUE?



NO



YES

\$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

\_\_\_\_\_ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

• INSPECTION REQUEST LINE: [www.co.kittitas.wa.us/cds/request.asp](http://www.co.kittitas.wa.us/cds/request.asp) or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506