



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00124

OWNER'S NAME: TYLER

DATE: 7/8/2016

TYPE: Rough-in mechanical

TIME STARTED: 1:36 PM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 20-15-29051-0052

1. All Other Framing OK.
2. NOTE: OWNER INTENDED TO REQUEST A FRAMING INSPECTION.
3. Shear Corrections OK.
4. Interior Shear OK.
5. OUTSTANDING CORRECTION NOT ADDRESSED. CUT TJI AND FRAYED ELECTRICAL WIRES NOT ADDRESSED.
6. OUTSTANDING CORRECTION NOT ADDRESSED. GAS LINE EXTENDED SINCE GAS LINE INSPECTION MUST BE TESTED. GAS LINE NOT ON TEST.

INSTRUCTIONS: OK to Insulate

NEXT INSPECTION: Insulation.

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: jeremy.haberman @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506