INSPECTION REPORT

INSPECTION REPORT			
PERMIT NUMBER:	BP-15-00143	OWNER'S NAME:	BV RESORT HOMES
DATE:	5/24/2016	TYPE:	Framing
TIME STARTED:	2:28 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-19051-0038		
 Hold down in corner of master bath not acceptably installed HDU2 missing to 6x6 post in bedroom adjacent to garage. page S1 Truss bracing A01, A02, A03, C02, C03, D02, G02, G03(is actually a G01) Complete correct install of hold down at entry window Stitch nail multiple members with hold downs connected Strap top plate at ech end over nook slider Plate nail all shear panels per shear schedule DWV on stack-ok INSTRUCTIONS: Complete above, ok to insulate walls			
NEXT INSPECTION: insulation/corrections			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:__

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iessica.contratto @co.kittitas.wa.us