## **INSPECTION REPORT**

| III CITOR RELOCK  |                                  |               |                 |
|---|----------------------------------|---------------|-----------------|
| PERMIT NUMBER:  | BP-15-00147                      | OWNER'S NAME: | ROWAN           |
| DATE:   | 7/12/2016                        | TYPE:         | Floor framing   |
| TIME STARTED:   | 9:20 AM                          | INSPECTOR:    | Jeremy Haberman |
| MAP NUMBER:   | 19-18-17010-0008                 |               |                 |
| 1. Drawings Not 2. Unable to Cor 3. Photos Saved  | nfirm Post to Beam Connection Po | er Plan.      |                 |
| INSTRUCTIONS: DO NOT COVER POST TO BEAM CONNECTION. CALL FOR REINSPECTION. HAVE DRAWINGS ONSITE.                    |                                  |               |                 |
| NEXT INSPECTION: REINSPECT  |                                  |               |                 |
| RE-INSPECTION FEE   | DUE? NO YES                      |               | \$              |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION                                    |                                  |               |                 |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: <u>jeremy.haberman</u> @co.kittitas.wa.us |                                  |               |                 |
|   |                                  |               |                 |

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506