## **INSPECTION REPORT**

PERMIT NUMBER:	BP-15-00147	OWNER'S NAME:	ROWAN
DATE:	11/30/2016	TYPE:	Framing
TIME STARTED:	2:09 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-18-17010-0008		
<ol> <li>NOTE: Inspection performed for Exterior Shear</li> <li>Exterior straps Ok per 14/S3</li> <li>NOTE: Framing inspection not performed - A35's and Gable Bracing not complete</li> </ol>			
INSTRUCTIONS:			
NEXT INSPECTION:	Framing		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS:	iustin.bennett @	
INSPECTION REQUEST LINE: 509-962-7694  http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			
nttp://www.co.kittitas.wa.us/cas/building/inspection-request.aspx			

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506