INSPECTION REPORT

PERMIT NUMBER:		BP-15-00171	OWNER'S NAME:	HABERMAN	
DATE:		6/3/2015	TYPE:	Mechanical and plumbir	
TIME STARTED:		1:43 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		18-19-31070-0004			
	4 1100 :- 1:-	1-			
	1. H2O is live-ok				
	2. DWV at 6#-ok				
	3. gas at 23#-ok				
	4. truss bracing A13, D06, D07. Marked on truss sheets				
	5. outlookers to have LSU24 hangers per plan. Or obtain engineer ok for omittance				
	6. obtain approval for porch rafter sistered on to trusses at front porch				
	7. Tempered window in master bath				
	8. fireplace not installed yet				
INSTRUCTIONS: ok to insulate, see corrections then					
NEXT INSPECTION: insulation and corrections					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2. Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 					