INSPECTION REPORT

PERMIT NUMBER: BP-15-00187 OWNER'S NAME: ROWLEY

DATE:	5/22/2015	TYPE:	Floor framing	
TIME STARTE	D: 9:34 AM	INSPECTOR:	Justin Bennett	
MAP NUMBE	r: 17-17-13020-0006			
1. Provide crawl space shown on drawing 2/9 on the Eastside				
2. Cr	2. Crawl access through pony walls Ok			
3. Flo	3. Floor Framing Ok			
4. Foundation vents Ok				
INSTRUCTIONS: Make correction above/Ok to cover when complete				
NEXT INSPECTION: Exterior Shear				
RE-INSPECTION	ON FEE DUE?	YES	\$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iustin_bennett @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 				
TIT IV. Nuby Street, Suite 2, Elicisburg, WA 30320 Wildin Office Line. 303-302-7300				