INSPECTION REPORT

TYPE:

PERMIT NUMBER: BP-15-00203

DATE:

7/10/2015

OWNER'S NAME: STRINGFELLOW

Floor framing

TIME STARTED:	3:01 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-17-32057-0002		
complete point load blocking where circled on plan			
2. A35 clips on 4x6 posts to sill plate on strip footing			
INSTRUCTIONS: verify above at next inspection			
NEXT INSPECTION: shearwalls			
RE-INSPECTION	FEE DUE? NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			