INSPECTION REPORT

PERMIT NUMBER:	BP-15-00203	OWNER'S NAME:	STRINGFELLOW
DATE:	9/16/2015	TYPE:	Framing and mechanica
TIME STARTED:	11:17 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-17-32057-0002		
1. outlookers to be at 24" oc per plan. Currently 2x4 48" oc			
2. gable brace every 48" per detail A/A7			
3. post down in overframing exceeding 4" height			
4. have insulation collar and chimney rough installed by insulation inspection			
5. strap top plate to glulam at kitchen entryway			
6. tempered window at soaker tub			
7. email stamped revision for header change at kitchen			
8. combustion air to be verified by final for woodstove			
9. mechanical ok			
INSTRUCTIONS: ok to insulate, see corrections then.			
NEXT INSPECTION: insulation			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			