INSPECTION REPORT

PERMIT NUMBER:	BP-15-00208	OWNER'S NAME:	FEASTER
DATE:	9/30/2015	TYPE:	Exterior shear
TIME STARTED:	10:51 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-24050-0112		
1. Hold dow	rns connecting to 2 studs, corre	ection to be seen by	framing inspection
2. gable ends not shearwalls. Windows per plan			
3. Note calls for egress window in loft. Check with plan review to deem necessity if			
storage only			
4. slab insulation visisble in shower area. Unable to verify rest of casita is insulated.			
Drill hole in each room			
INSTRUCTIONS: ok to cover exterior			
NEXT INSPECTION: mechanical/ corrections			
RE-INSPECTION FEE	DUE? V NO YE	S	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			